Oil Field Environmental Incident Summary

Responsible Party: MARATHON OIL COMPANY **Well Operator:** MARATHON OIL COMPANY

Well Name: RUFUS USA 21-4TFH

Field Name: REUNION BAY Well File #: 30514

Date Incident:7/24/2015Time Incident:02:00Facility ID Number:County:MOUNTRAILTwp: 150Rng: 93Sec: 4Qtr:

Location Description:

Submitted By: Christopher Gitch Received By:

Contact Person: Chris Gitch

3172 HWY 22 N

DICKINSON, ND 58601

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 8 Barrels 8 Barrels 8 barrels

Other

Description of Other Released Contaminant:

N/A

Inspected: Written Report Received: 8/11/2015 Clean Up Concluded: 7/24/2015

Risk Evaluation:

No immediate risk. Fluid has been cleaned up.

Areal Extent:

Spill contained on secondary containment

Potential Environmental Impacts:

Minimal potential environmental impacts. Spilled fluid has been cleaned up.

Action Taken or Planned:

Spill was contained on matting boards and all fluid was cleaned up by contractor. Fluids were put into a storage tank for disposal.

Wastes Disposal Location: At approved facility by contractor.

Agencies Involved:

Updates

Date: 7/24/2015 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained on location according to the report. NDIC retains oversight.